

100CX
Magnification calibration

Microscope Magnification	True Magnification
2,600	2,600
3,300	3,500
5,000	5,000
6,600	6,800
8,300	9,100
10,000	10,800
13,000	14,300
16,000	17,900
20,000	21,700
26,000	28,900
33,000	36,300
50,000	54,000
66,000	65,700
100,000	105,800
130,000	132,500